

1989 - Porsche 928 S4 Coupe

Chassis number (VIN): WFXXXXXXXX969

Registration number: X

ID: COMMODY_3867



1989 - Porsche 928 S4 Coupe

VEHICLE DETAILS

MAKE	Porsche
MODEL	928 S4
TYPE	Coupe
CONSTRUCTION YEAR	1989
MILEAGE	137158 km
CHASSIS NUMBER (VIN)	██████████ 969
VALID MOT	Yes
FIRST ADMISSION DATE	1989
REGISTRATION NUMBER	██
ORIGINAL REGISTRATION PLATES	No
REGISTRATION COUNTRY	LT
LAST REGISTRATION DATE	2023

EXTERIOR

OVERALL QUALITY OF THE CAR	2.Excellent
BODY CONDITION	2.Excellent
FRONT BUMPER CONDITION	2.Excellent
REAR BUMPER CONDITION	2.Excellent
CHROME TRIM CONDITION	Not applicable
CONVERTIBLE	No
CONVERTIBLE HOOD CONDITION	Not applicable
DAMAGES OR SPOTS VISIBLE ON THE BODY?	No
IRREGULARITIES IN THE SEAMS OF THE BODY?	Not applicable
LIGHT RUST	No
HEAVY RUST	No
PAINT DAMAGES	No
COLOUR DIFFERENCES	No
WINDOW COLOUR	Transparent
WINDOW CONDITION	2.Excellent
FRONT LIGHTS CONDITION	2.Excellent
REAR LIGHTS CONDITION	2.Excellent
HAS THE BODY OF THE VEHICLE BEEN RESTORED?	Yes

DESCRIPTION OF RESTORATION

The vehicle was subject to body restoration, during which the front and rear bumpers were replaced with new genuine parts. The interior upholstery was re-trimmed, and a new factory-original engine was acquired and installed in place of the previous.

1989 - Porsche 928 S4 Coupe

ENGINE, GEARBOX AND EXHAUST

ENGINE MATCHING NUMBERS	No
ENGINE STARTS	Yes
STATIONAIRY RUN	Good
ENGINE REVVING	Good
ENGINE AND COMPARTMENT	2.Excellent
FUEL TYPE	Petrol
GEARBOX TYPE	Automatic
AMOUNT OF GEARS	4
GEARBOX CONDITION	Good
CLUTCH CONDITION	Good
EXHAUST MATERIAL	Stainless steel
EXHAUST CONDITION	Good

WHEELS, TIRES AND BRAKES

FRONT BRAKE TYPE	Disc brakes
FRONT BRAKE CONDITION	Good
REAR BRAKE TYPE	Disc brakes
REAR BRAKE CONDITION	Good
ABS	Yes
RIM TYPE	Light metal
SPARE WHEEL	Yes
CONDITION SPARE WHEEL	2.Excellent
CONDITION SUSPENSION	Good
CONDITION SHOCK ABSORBERS	Good
STEERING GEAR	LHD
STEERING GEAR CONDITION	Good
POWER STEERING	Yes

1989 - Porsche 928 S4 Coupe

IMAGES



1989 - Porsche 928 S4 Coupe

IMAGES



1989 - Porsche 928 S4 Coupe

INTERIOR

INTERIOR CONDITION	2.Excellent
UPHOLSTERY TYPE	Leather
UPHOLSTERY COLOR	Black
ORIGINAL UPHOLSTERY	No
CONDITION OF THE UPHOLSTERY	2.Excellent
CONDITION OF THE DASHBOARD	2.Excellent
ORIGINAL GAUGES	Yes
CONDITION OF THE INSTRUMENT PANEL	2.Excellent
RADIO PRESENT	Yes
ORIGINAL RADIO	Yes
ALARM SYSTEM	Yes
ALARM SYSTEM CLASSIFICATION	Factory standard Class 1
TRACK & TRACE	No
FIRE EXTINGUISHER	Yes

DOCUMENTATION

ORIGINAL HANDBOOK	No
MAINTENANCE BOOK	No
WARRANTY CARD	No
ORIGINAL REGISTRATION CERTIFICATE	No
ORIGINAL PURCHASE INVOICE	Yes
IS THE VEHICLE IMPORTED	Yes
IMPORT DOCUMENTS	No
YEAR OF IMPORT	Not applicable

EXTRA INFORMATION PROVIDED BY THE CLIENT

Stored in [REDACTED] in Vilnius, Lithuania.

The engine was replaced at Porsche center Vilnius (07/2021) They gave back the old engine, got a new one in. The new engine was installed when the car mileage was 135454 km.

Other details that were done in Porsche center Vilnius: Cardan shaft replaced, Classic multimedia installed, new rims installed (01/2020) and full body repaint (01/2020).

1989 - Porsche 928 S4 Coupe

VALUATION

CUSTOMER NAME



CUSTOMER E-MAIL



commodity.com

EXPERT

S. Peereboom

LOCATION

Amsterdam, The Netherlands

THE VALUE OF YOUR CAR

€ 52.500